

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20101110 WWW.					
Inspection Date	2019	11	23	Report Number	20191119-WMATA-KEK-9					
Rail Agency Name	Washington Metropolitan Area Transit Authority		Rail Agency Department	WMATA – ATC	Sub- Department		ATC Compliance			
	Name			Email	Office Phone		Mobile Phone			
Rail Agency Department										
Contact Information										
Inspection Location	N06 – Wiehl	e-Reston East	Station							

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	STC-OBS-QAI					
Inspection Units	5					
Inspection Subunits	0					
Defects (Number)	0					
Recommended Finding	0					
Remedial Action Required ¹	NO					
Recommended Reinspection	NO					

Activity Summaries

Inspection Activity #	1 Inspection Subject Track Ins			spection Verification Observation				Activity Code		TR	K	OBS	WI	
Job Briefing Employee Name/Title	MCAP RWIC				Accompanied Inspector?		YES	Out Brief Conducted	YES	Time	080	00	Outside Shift	NO
Related Reports	N/A				Related CAPS / Findings N/A									
	Ref Rule o			Rule or S	SOP Standard				Other / Title			Checklist Reference		
Related Rules, SOPs, Standards, or Other	RWPM													
Standards, or Strict														
Inspection Location	Main Track	Yard	Stati	ion (occ	RTA Facility	WMSC Office	Tue als Toma	At-grad	At-grade Tunnel		Elevated		N/A
	Х		Х			ATC	Track Type							
Line(a)	Nilina	Track		#1 & 2		Chain Marker		From		То				
Line(s)	N-Line Number		er	#1 & 2		and/or St	and/or Station(s) N06 (SilverLii		ne) CM-1079+67 +/- CM-		I-1091+07 +/-			
Vehicles	Head Car Number		ı	Number of Cars										
	N/A			N/A		Equipment		N/A						
Description	Shut Down for N Line N04 Spring Hill Rd., to N06				N06 Wiehl	e-Reston Eas	st, Track 1 & 2	Number	of Defect	s			0	

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		Date
KEMMERY E. KENDRICK		11.23.2019
Inspector in Charge – Name	Inspection Team	
KEMMERY E. KENDRICK	WASHINGTON METRORAIL SAFETY COMMISSION	

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	MASS Electric, CRC, and ATCM personnel – under the direction of MCAP RWIC;	Recommended Finding?	NO
	did perform verification of wiring (ringing of cables) and relay testing. The location was reported as N06 1079+67 +/- (Wiehle-Reston East Station) to	Remedial Action Required?	NO
	 Wiring verification and pulling of cables started 11.23.19, approx. 0400hrs and ended 11.25.19. Notable Observations: MASS Electric (B&C sub-contractors) were performing wiring verification in the TCR, pulling cable wayside, and terminating loops for Push Button Junction boxes on and about Tracks 1 & 2 0800hrs TCR - J1 rack was complete and crews were starting N1 and S1 racks ATC Relay Production Test Crew were performing relay testing inside the TCR Cable that had been buried ONLY ½" from the troth to Tracks 1 & 2 were re-dug to WMATA 3' deep Wayside standards Cables were being pulled from the loops at the troths to the junction boxes of the push buttons (pictures below) Other departments taking advantage of the Shut-Down: TSSM – Track & Structure System Maintenance, ATCM – 7 members, IRPG – Infrastructure Renewal, Escalator & Elevator department, MASS and CRC All Joint Venture members complied with PPE and RWP rules. 	Recommended Reinspection?	NO
Remedial Action			

Photos:...





Form WMSC-IR-1 Version date: 10/5/18